

Behringer WING Firmware Update

Version 3.1.1 (01 June 2026)

Added

- User Patches now include Gain and Phantom Power control for assigned Sources.
- Send Spill button on the BUS HOME page
- PAN control on Send Faders
- Pressing EFFECTS + METERS after shutdown resumes console operation without requiring a reboot
- Hold UTILITY after selecting multiple Sources by sliding across the screen to add or remove Sources
- Gain and Phantom Power control over StageConnect for new StageConnect-based I/O interfaces

Changed

- User Patches now follow the mute and polarity status of their assigned Sources (in addition to their own mute and polarity settings)
- Assigned channel is now selected when touching Send Faders on the FADERS screen
- "Dry" switch label to the ULTRA ENHANCER and PSYCHO BASS effects
- DUCKER Hold time increased to 30 seconds
- Playlist selection now advances to the next item after an automatic Stop
- If no Scene is selected, pressing GO NEXT or GO PREV now always loads Scene #1
- Send Faders Spill now uses channel faders when all sends are set to GROUP mode
- Default setting of the LIMITER in the MASTERING plugin changed to Off
- SETUP screen layout updated to accommodate future enhancements

Fixed

- Layer names were not updated automatically when changed remotely
- Older Snapshots containing the Aux Channel Dynamics Combo plugin were not loading correctly
- CC assignments to DCA MUTE, DCA FADER, and MUTE GROUP were not loading correctly
- The TAPE MACHINE effect in the MASTERING plugin now uses the same settings as the standalone TAPE MACHINE effect
- Customization Link used incorrect colors for gray and white